Tree Survey

Ref.	Tag	Species	Height	Branch Spread (radius)	Life Stage	Vitality	Structural	Additional Notes	Management Recommendations	Priority Works	Priority	Due Date	TPO/CA	W3W	Quote 1	Quote 2	Quote 3
T1	90622	Quercus robur (English oak)	8-12 m	6 5	Early-Mature	Good	Good	The tree is growing in a parkland. Low branches over grass. Bench around the stem of the tree. Minor deadwood (<50mm diameter) in crown.		Prune tree to provide a ground clearance of 2 metres removing only the tertiary branches.	IBA		CA	confident.tight.pasting			
T2	90633	Prunus spp (Cherry plum)	<8 m	6	Early-Mature	Good	Fair	A minor roadway is north of the tree. Stem separates into multiple stems at 0.5 metres. Minor deadwood (<50mm diameter) in crown. Water pump under canopy.					CA	worm.evolution.geek			
T3	90644	Sorbus aria (Whitebeam)	<8 m	4 5	Early-Mature	Good	Fair	A minor roadway is north of the tree. A footpath is east of the tree. Stem separates into multiple stems at 1 metre. Minor deadwood (<50mm diameter) in crown.					CA	zipped.inclines.works			
T4	90655	Acer platanoides (Norway Maple)	<8 m	3	Early-Mature	Fair	Fair	A footpath is east of the tree. Stem separates into multiple stems at 1 metre. Dieback in the crown of the tree. Minor deadwood (<50mm diameter) in crown (Broadly acceptable risk - code 344).	Prune out deadwood.				CA	generally.wage.washed			
T5	90900	Acer platanoides (Norway Maple)	12-15 m	6	Mature	Good	Good	A footpath is east of the tree. Stem separates into multiple stems at 2 metres - included unions present - not of concern at this point in time. Tree appears to be suffering from drought stress (foliage loss).					CA	truck.heaven.statue			
T7	90888	Acer platanoides (Norway Maple)	12-15 m	4 5	Early-Mature	Fair	Good	A footpath is east of the tree. Stem separates into multiple stems at 2 metres. Minor deadwood (<50mm diameter) in crown. Minor dieback in crown.					CA	fiery.bins.ranking			
T8	90887	Fraxinus angustifolia (Narrow-leaved ash)	12-15 m	5 5	Early-Mature	Good	Good	A footpath is east of the tree. Minor deadwood (<50mm diameter) in crown. Epicormic growth on stem of tree.	Remove epicormic growth from base and lower stem.				CA	guideline.sway.shade			
T9	90885	Acer platanoides (Norway Maple)	12-15 m	8	Mature	Good	Good	A footpath is east of the tree. Stem separates into multiple stems at 2 metres. Minor deadwood (<50mm diameter) in crown (Broadly acceptable risk - code 344). Heavily included union at secondary point of branching over bench - prune out the included branch closest to the bench (Unacceptable risk of harm).		Prune out included branch over bench.	12 Months	Aug-27	CA	both.misfits.ballpoint			
T10	90884	Sorbus intermedia (Swedish whitebeam)	8-12 m	4 5	Early-Mature	Fair	Fair	A footpath is east of the tree. Stem separates into multiple stems at 1.5 metres. Tree is suppressed by surrounding trees. Tree possesses an asymmetrical crown - not of concern at this point in time. Moderate size deadwood (<150mm diameter) in crown.		Remove significant deadwood (>30mm diameter and 1m in length).	IBA		CA	gliding.flashback.shame			
T11	90883	Acer platanoides (Norway Maple)	12-15 m	6	Early-Mature	Good	Good	A footpath is east of the tree. Stem separates into multiple stems at 2 metres. Minor deadwood (<50mm diameter) in crown (Broadly acceptable risk - code 344).					CA	agency.gets.whiplash			
T12	90882	Acer platanoides (Norway Maple)	12-15 m	6 5	Early-Mature	Good	Good	A footpath is east of the tree. Stem bifurcates at 2.5 metres. Minor deadwood (<50mm diameter) in crown (Broadly acceptable risk - code 344).					CA	paving.rescue.tradition			

Tree Survey

Ref.	Tag	Species	Height	Branch Spread (radius)	Life Stage	Vitality	Structural	Additional Notes	Management Recommendations	Priority Works	Priority	Due Date	TPO/CA	W3W	Quote 1	Quote 2	Quote 3
T13	90811	Sorbus aucuparia (Rowan)	8-12 m	2 5	Early-Mature	Fair	Fair	A footpath is east of the tree. Stem separates into multiple stems at 1 metre. Dieback in the crown of the tree over bench. Minor deadwood (<50mm diameter) in crown (Broadly acceptable risk - code 344). Epicormic growth at base of tree.	Remove epicormic growth from base and lower stem. Prune out deadwood.				CA	commands.relate.hedgehog			
T14	90800	Acer platanoides (Norway Maple)	12-15 m	6	Early-Mature	Good	Fair	A footpath is east of the tree. Stem separates into multiple stems at 2.5 metres. Minor deadwood (<50mm diameter) in crown. Tree possesses an asymmetrical crown due to recent tree removal - not of concern at this point in time. Minor sized cambial damage on branch - not of concern at this point in time. Tight unions present in crown - with increased likelihood of branch failure - low risk of harm.					CA	swordfish.curtail.encourage			
T15	90778	Acer platanoides (Norway Maple)	12-15 m	6	Early-Mature	Good	Good	A footpath is east of the tree. Minor deadwood (<50mm diameter) in crown. Epicormic growth on stem of tree.	Remove epicormic growth from base and lower stem.				CA	panoramic.animated.bother			
T16	90777	Tilia x Europaea (Common Lime)	8-12 m	3	Early-Mature	Good	Fair	A footpath is west of the tree. Stem bifurcates at 2 metres. Tight union - Low risk of failure at present. Historical cambium damage. Moderate decay in the stem of the tree. The tree possesses a lean towards the south east - not of concern at this point in time.					CA	voices.verifying.diamond			
T17	90776	Acer pseudoplatanus (Sycamore)	12-15 m	5	Mature	Good	Good	A footpath is west of the tree. Stem bifurcates at 2 metres. Stem bifurcates again at 4 metres. Historical cambium damage - not of concern at this point in time.					CA	optimally.hardens.crisper			
T18	-	Fraxinus excelsior (Ash)	<8 m	0 25	Young	Good	Good		Bark mulch should be applied to a depth of 50mm around the base of the tree forming a 1m radius circle around the tree's stem.				CA	hacksaw.regarding.dove			
T19	90755	Acer pseudoplatanus (Sycamore)	12-15 m	5 5	Early-Mature	Good	Good	A footpath is west of the tree.					CA	compelled.tides.massing			
T20	90744	Tilia x Europaea (Common Lime)	12-15 m	5	Early-Mature	Good	Good	A footpath is west of the tree. Stem bifurcates at 2 metres.					CA	requiring.narrow.flesh			
T21	90733	Prunus avium (Cherry)	8-12 m	5	Early-Mature	Fair	Good	A footpath is west of the tree. Stem bifurcates at 2 metres. Minor deadwood (<50mm diameter) in crown. Tree possesses an asymmetrical crown - not of concern at this point in time.					CA	troubles.boards.holds			
T22	90722	Alnus glutinosa (Common alder)	15-20 m	4	Mature	Good	Good	A footpath is west of the tree. Dense canopy obscuring the full visual inspection of the upper portion of the tree. Historical cambium damage - not of concern at this point in time. Minor deadwood (<50mm diameter) in crown (Broadly acceptable risk - code 344).		Deadwood can be removed to prevent minor nuisance or for aesthetics.	IBA		CA	womb.providing.pronouns			

Tree Survey

Ref.	Tag	Species	Height	Branch Spread (radius)	Life Stage	Vitality	Structural	Additional Notes	Management Recommendations	Priority Works	Priority	Due Date	TPO/CA	W3W	Quote 1	Quote 2	Quote 3
T23	9071	Aesculus hippocastanum (Horse chestnut)	12-15 m	5	Early-Mature	Fair	Good	A footpath is west of the tree. Stem bifurcates at 2 metres. Bleeding canker of horse chestnut (Pseudomonas syringae pv. aesculi) was observed. Epicormic growth on stem of tree.	Remove epicormic growth from base and lower stem.				CA	rainbow.deflated.waking			
T24	9070	Tilia x Europaea (Common Lime)	15-20 m	5	Early-Mature	Good	Good	A footpath is west of the tree. Dense canopy obscuring the full visual inspection of the upper portion of the tree. Stem bifurcates at 2.5 metres. Minor deadwood (<50mm diameter) in crown.					CA	fend.reflected.seeing			
T25	9068	Sorbus intermedia (Swedish whitebeam)	<8 m	2	Semi-Mature	Fair	Fair	A footpath is west of the tree. Moderate sized cambial damage at the base of the tree. Minor deadwood (<50mm diameter) in crown.					CA	butterfly.clashes.sounds			
T26	9067	Sorbus intermedia (Swedish whitebeam)	<8 m	4	Early-Mature	Good	Fair	A footpath is west of the tree.					CA	misted.hence.mole			
T27	5900	Sorbus aucuparia (Rowan)	<8 m	0 25	Young	Poor	Fair	Tree suffering from significant drought damage and stress. Tree lacks future potential.		Remove and replace with a tree of the same species.	IBA		CA	airtime.scatters.lectures			
T28	9060	Acer platanoides (Norway Maple)	<8 m	3 5	Early-Mature	Good	Good	Memorial tree.					CA	rises.cloud.quote			
T29	578	Fagus sylvatica (Beech)	<8 m	2 25	Semi-Mature	Good	Good	Stem separates into multiple stems at 0.5 metres. Mower/strimmer damage at base. Low branch tips.	Bark mulch should be applied to a depth of 50mm around the base of the tree forming a 1m radius circle around the tree's stem. The mulch should not be heaped up around the stem of the tree.	Crown lift to 1.5m.	IBA		CA	locked.owned.tugging			
T30	9058	Acer platanoides 'Drummondii' (Norway Maple)	<8 m	3	Semi-Mature	Good	Good	Minor ivy on the stem of the tree - not of concern at this moment in time.					CA	lasts.saves.renovated			
T31	9059	Acer platanoides (Norway Maple)	<8 m	3 5	Semi-Mature	Good	Good	Minor dieback in crown.					CA	pastels.tasters.headings			
T32	531	Quercus ilex (Holm oak)	<8 m	0 25	Young	Good	Good		Bark mulch should be applied to a depth of 50mm around the base of the tree forming a 1m radius circle around the tree's stem.				CA	wonderful.dignify.fried			
T33	513	Fraxinus angustifolia (Narrow-leaved ash)	8-12 m	3 5	Early-Mature	Good	Good						CA	worldwide.shorts.mulled			
T34	547	Acer platanoides 'Crimson King' (Norway Maple)	<8 m	2 5	Semi-Mature	Good	Fair	Tight heavily included union at 1.5m - removal of secondary limb advised to avoid future issues.		Remove secondary stem to avoid future structural issues.	IBA		CA	sunblock.terms.strongly			
T35	596	Acer platanoides 'Crimson King' (Norway Maple)	<8 m	2 5	Semi-Mature	Good	Good						CA	postcard.whirlpool.incomes			

Tree Survey

Ref.	Tag	Species	Height	Branch Spread (radius)	Life Stage	Vitality	Structural	Additional Notes	Management Recommendations	Priority Works	Priority	Due Date	TPO/CA	W3W	Quote 1	Quote 2	Quote 3
T36	9158	Acer pseudoplatanus (Sycamore)	15-20 m	8	Late-Mature	Fair	Fair	A minor roadway is west of the tree. Minor ivy on the stem of the tree - not of concern at this moment in time. The canopy has been reduced in the past - repeated prune not currently required, but may be advisable in 2-3 years. Moderate size deadwood in central crown (<150mm diameter) in crown (Unacceptable risk where imposed on others - code 323). Green waste around base of tree obscuring full assessment of roadside buttresses. Tree is understood to be highly valued by locals - mulching within the dripline advised to help maintain high tree vitality, particularly during dry summer months.	Bark mulch should be applied to a depth of 50mm around the base of the tree forming a 5m radius circle around the tree's stem. To improve vitality. Remove green waste from around base.	Remove significant deadwood (>30mm diameter and 1m in length).	24 Months	Aug-28	CA	outnumber.bulk.testers			
T37	9159	Acer campestre (Field maple)	8-12 m	5	Early-Mature	Good	Good	A minor roadway is west of the tree. Tree growing beneath crown of T36.					CA	enlighten.harnessed.riper			
T38	574	Quercus robur (English oak)	<8 m	0 25	Young	Good	Good	Sapling. Memorial tree.	Bark mulch should be applied to a depth of 50mm around the base of the tree forming a 1m radius circle around the tree's stem. The mulch should not be heaped up around the stem of the tree.				CA	inversely.appetite.badly			
T39	557	Prunus cerasifera (Cherry plum)	<8 m	0 5	Young	Good	Good		Bark mulch should be applied to a depth of 50mm around the base of the tree forming a 1m radius circle around the tree's stem. The mulch should not be heaped up around the stem of the tree.				CA	rewriting.salmon.invented			
T40	502	Quercus petraea (Sessile Oak)	<8 m	1 5	Young	Good	Good	Low branching on stem.	Bark mulch should be applied to a depth of 50mm around the base of the tree forming a 1m radius circle around the tree's stem. The mulch should not be heaped up around the stem of the tree. Clear stem of branching up to 1.5m.				CA	relocated.restriction.bets			
T41	5040	Acer platanoides (Norway Maple)	8-12 m	5 5	Early-Mature	Good	Fair	A minor roadway is west of the tree. Stem separates into multiple stems at 2 metres. Phone line running through tree crown - no work needed. Low branch tips. Tight included bark unions present at primary points of bifurcation - posing increased likelihood of failure - risk can be managed by periodic all-over crown reductions - reduction regime not currently required - likely advisable from 2029.		Crown lift to 2m.	IBA		CA	laminated.removals.variation			
T42	885	Sorbus aria (Whitebeam)	<8 m	2 75	Semi-Mature	Good	Good	Minor sized cambial damage - not of concern.					CA	geology.fool.flotation			
T43	1981	Acer platanoides 'Drummondii' (Norway Maple)	<8 m	1	Young	Good	Good	Some reversion observed.	Bark mulch should be applied to a depth of 50mm around the base of the tree forming a 1m radius circle around the tree's stem. The mulch should not be heaped up around the stem of the tree.				CA	bearings.tightest.cobble			

Tree Survey

Ref.	Tag	Species	Height	Branch Spread (radius)	Life Stage	Vitality	Structural	Additional Notes	Management Recommendations	Priority Works	Priority	Due Date	TPO/CA	W3W	Quote 1	Quote 2	Quote 3
T44	597	Acer campestre (Field maple)	12-15 m	5 5	Early-Mature	Good	Good	A minor roadway is west of the tree. Minor deadwood (<50mm diameter) in crown. Phone line running through tree crown with tension and rubbing of the line. Low branch tips. Councillor request to reduce tree to maintain a tidy aesthetic.		Reduce tension and rubbing on the phone line by pruning tertiary branches to give 0.2 - 0.5m of clearance. Prune to give 2.25m clearance from the ground. Reduce tree by ~2m in height and 1.5m laterally - for aesthetics.	IBA		CA	converter.quoted.irrigated			
T45	584	Acer campestre (Field maple)	8-12 m	5 5	Early-Mature	Good	Good	Dense ivy on tree structure, obscuring full visual assessment. Dense canopy obscuring the full visual inspection of the upper portion of the tree. A minor roadway is west of the tree. Minor deadwood (<50mm diameter) in crown.	Sever the ivy at the base of the tree by removing a 30cm strip. Care must be taken not to damage the cambium of the tree while removing the ivy.				CA	engraving.prayers.manliness			
T46	-	Crataegus monogyna (Hawthorn)	<8 m	3	Mature	Fair	Fair	The tree is growing in a hedge. Minor deadwood (<50mm diameter) in crown. Dense ivy on tree structure, obscuring full visual assessment.	Sever the ivy at the base of the tree by removing a 30cm strip. Care must be taken not to damage the cambium of the tree while removing the ivy.				CA	stewing.readings.rejoins			
T47	511	Crataegus monogyna (Hawthorn)	<8 m	3	Mature	Fair	Fair	The tree is growing in a hedge. Minor deadwood (<50mm diameter) in crown.					CA	shape.tunnel.repayment			
T48	555	Crataegus monogyna (Hawthorn)	<8 m	2	Mature	Fair	Fair	The tree is growing in a hedge. Minor deadwood (<50mm diameter) in crown. Dense ivy on tree structure, obscuring full visual assessment.					CA	expiring.custard.impeached			
T49	538	Crataegus monogyna (Hawthorn)	<8 m	3	Mature	Fair	Fair	Twin-stemmed tree. The tree is growing in a hedge. Minor deadwood (<50mm diameter) in crown. Epicormic growth on stem of tree.					CA	angry.hungry.deadline			
T50	520	Crataegus monogyna (Hawthorn)	<8 m	3 25	Mature	Fair	Fair	Twin-stemmed tree. The tree is growing in a hedge. Minor dieback in crown. Minor deadwood (<50mm diameter) in crown. Dense ivy on tree structure, obscuring full visual assessment.	Sever the ivy at the base of the tree by removing a 30cm strip. Care must be taken not to damage the cambium of the tree while removing the ivy.				CA	buffoon.anchorman.stow			
T51	589	Crataegus monogyna (Hawthorn)	<8 m	3	Mature	Poor	Fair	The tree is growing in a hedge. Moderate dieback in crown. Minor deadwood (<50mm diameter) in crown. Dense ivy on tree structure, obscuring full visual assessment.	Sever the ivy at the base of the tree by removing a 30cm strip. Care must be taken not to damage the cambium of the tree while removing the ivy. Bark mulch should be applied to a depth of 50mm around the base of the tree forming a 3m radius circle around the tree's stem. To improve vitality.				CA	figure.cloud.speedily			
T52	-	Crataegus monogyna (Hawthorn)	<8 m	3	Mature	Fair	Fair	The tree is growing in a hedge. Minor deadwood (<50mm diameter) in crown. Dense ivy on tree structure, obscuring full visual assessment.	Sever the ivy at the base of the tree by removing a 30cm strip. Care must be taken not to damage the cambium of the tree while removing the ivy.				CA	swims.shackles.reporters			
T53	-	Crataegus monogyna (Hawthorn)	<8 m	3	Mature	Fair	Fair	Twin-stemmed tree. A full assessment of the tree was impeded due to access restrictions. The tree is growing in a hedge. Minor deadwood (<50mm diameter) in crown. Minor decay in the stem of the tree - not of concern at this moment in time.	Sever the ivy at the base of the tree by removing a 30cm strip. Care must be taken not to damage the cambium of the tree while removing the ivy.				CA	desk.cringes.returns			

Tree Survey

Ref.	Tag	Species	Height	Branch Spread (radius)	Life Stage	Vitality	Structural	Additional Notes	Management Recommendations	Priority Works	Priority	Due Date	TPO/CA	W3W	Quote 1	Quote 2	Quote 3
T54	-	Crataegus monogyna (Hawthorn)	<8 m	3	Mature	Fair	Fair	Twin-stemmed tree. Minor deadwood (<50mm diameter) in crown. Dense ivy on tree structure, obscuring full visual assessment. Tree is suppressed by surrounding trees. Minor decay at the base of the tree - not of concern at this moment in time.					CA	visit.sage.stilted			
T55	-	Quercus robur (English oak)	<8 m	0 2	Young	Good	Good	Sapling.	Bark mulch should be applied to a depth of 50mm around the base of the tree forming a 1m radius circle around the tree's stem.				CA	value.yesterday.custom			
T56	1982	Malus domestica (Apple)	<8 m	1 5	Young	Good	Good	Memorial tree. Tree support stake and tie in place.					CA	flashback.glow.soon			
T57	1978	Acer campestre (Field maple)	<8 m	2 75	Semi-Mature	Good	Good	Subdominant to T36. Epicormic growth at base of tree.	Remove epicormic growth from base and lower stem.				CA	parties.toast.parked			
T58	1979	Prunus 'Kanzan' (Kanzan cherry)	<8 m	0 5	Young	Good	Good	Tree support stake and tie in place.	Bark mulch should be applied to a depth of 50mm around the base of the tree forming a 1m radius circle around the tree's stem.				CA	suits.third.airstrip			
T59	1980	Prunus 'Kanzan' (Kanzan cherry)	<8 m	0 5	Young	Good	Good	Tree support stake and tie in place.	Bark mulch should be applied to a depth of 50mm around the base of the tree forming a 1m radius circle around the tree's stem.				CA	intensely.bluff.converged			
G1	-	Mixed native trees	12-15 m	-	Mature	Good	Good	Ownership of the trees is unknown. A belt of trees on the far side of the boundary fence. Features include: Deadwood 50mm or greater in diameter; epicormic growth; tight unions and poor growing forms. Vegetation growing at the base of the trees. A full assessment of the trees was impeded due to access restrictions. A driveway is east of the trees. A play park is west of the trees. Species include: Acer pseudoplatanus, Tilia × europaea, Acer platanoides 'Crimson King', Betula pendula, Cupressus spp with an understory of Ulmus spp. Dense ivy on some of the group's structure, obscuring full visual assessment. Small dead standing trees present within group (Broadly acceptable risk - code 344).					CA	See Tree Location Plan			
G2	-	Ulmus spp. (Elm)	<8 m	-	Semi-Mature	Poor	Poor	Cluster of small elm trees, multiple dead specimens. Trees adjacent to play park.		Remove dead elm trees.	IBA		CA	See Tree Location Plan			
G3	-	Mixed species	<8 m	-	Semi-Mature	Good	Good	A dense group of Prunus spp and Fraxinus spp. Vegetation growing at the base of the trees.					CA	See Tree Location Plan			
G4	-	Mixed species	<8 m	-	Semi-Mature	Good	Good	Bushy hedge group.					CA	See Tree Location Plan			
G6	-	Betula spp (Birch)	<8 m	-	Young	Good	Good	Cluster of 7 trees - 6 birch, 1 contorted willow. Memorial group.					CA	See Tree Location Plan			

Tree Survey

Ref.	Tag	Species	Height	Branch Spread (radius)	Life Stage	Vitality	Structural	Additional Notes	Management Recommendations	Priority Works	Priority	Due Date	TPO/CA	W3W	Quote 1	Quote 2	Quote 3
G7	-	Mixed native trees	<8 m	-	Early-Mature	Good	Good	This group is a hedge. Species include: Crataegus monogyna, Taxus baccata, Sambucus nigra, Ulmus spp. Semi-recently planted infill of Crataegus monogyna, Malus domestica, Viburnum spp, dog rose (Rosa canina), Salix spp, Corylus avellana, Pinus sylvestris. Minor deadwood (<50mm diameter) in crown. Occasional small dead tree - not of concern at this point in time.					CA	See Tree Location Plan			